ATTACHMENT C

APPROVED LABORATORY METHODS

APPROVED ANALYTICAL METHODS FOR ORGANIC COMPOUNDS

ANALYTE	SOLID A	ND HAZARDOUS WASTE METHODS		WATER METHODS			
	No.	PARAMETER		No.	PARAMETER		
Benzene	8020*	Aromatic Volatile Organics	1	502.2	Volatile Org. Cmp., Purgeable Org. Cmp.		
	8021*	Halogenated and Aromatic Volatiles		503.1	Volatile Aromatic & Unsat. Organic Cmp.		
	8240	Volatiles			Purgeable Organic Compounds		
	8260	Volatiles		524.2	Purgeable Organic Compounds		
					Purgeable Aromatics		
					Purgeables		
					Volatile Organic Compounds		
BTEX	8020*	Aromatic Volatile Organics	1		Volatile Org. Cmp., Purgeable Org. Cmp.		
	8021*	Halogenated and Aromatic Volatiles			Volatile Aromatic & Unsat. Organic Cmp.		
	8240	Volatiles			Purgeable Organic Compounds		
	8260	Volatiles			Purgeable Organic Compounds		
1,2-DCA	8010*	Halogenated Volatile Organics	1		Volatile Halogenated Organic Compounds		
1,2-DCA	8021*	Haloginated and Aromatic Volatiles			Volatile Org. Cmp., Purgeable Org. Cmp.		
	8240	Volatiles			Purgeable Organic Compounds		
	8260	Volatiles			Purgeable Organic Compounds		
	0200	Volatiles			Halogenated Volatile Organics		
					S		
					Purgeables		
	0000*		4		Volatile Organic Compounds		
Ethylbenzene	8020*	Aromatic Volatile Organics			Volatile Org. Cmp., Purgeable Org. Cmp.		
	8021*	Haloginated and Aromatic Volatiles			Volatile Aromatic & Unsat. Organic Cmp.		
	8240	Volatiles			Purgeable Organic Compounds		
	8260	Volatiles			Purgeable Organic Compounds		
					Purgeable Aromatics		
					Purgeables		
			4	1624	Volatile Organic Compounds		
MtBE	8020*	Aromatic Volatile Organics		503.1	Volatile Aromatic & Unsat. Organic Cmp.		
	8240*	Halogenated and Aromatic Volatiles					
	8260	Volatiles					
Naphthalene	8021*	Halogenated and Aromatic Volatiles		502.2	Volatile Org. Cmp., Purgeable Org. Cmp.		
	8100	Polynuclear Aromatic Hydrocarbons		503.1	Volatile Aromatic & Unsat. Organic Cmp.		
	8250	Semivolatile Organic Compounds		524.2	Purgeable Organic Compounds		
	8270	Semivolatile Organic Compounds		550	Polycyclic Aromatic Hydrocarbons		
	8310	Polynuclear Aromatic Hydrocarbons		550.1	Polycyclic Aromatic Hydrocarbons		
	8260	Volatiles		610	Polynuclear Aromatic Hydrocarbons		
				625	Base/Neutrals & Acids		
				1625	Semivolatile Organic Compounds		
Toluene	8020*	Aromatic Volatile Organics			Volatile Org. Cmp., Purgeable Org. Cmp.		
	8021*	Halogenated and Aromatic Volatiles			Volatile Aromatic & Unsat. Organic Cmp.		
	8240	Volatiles			Purgeable Organic Compounds		
	8260	Volatiles			Purgeable Organic Compounds		
	3200	100			Purgeable Aromatics		
					Purgeables		
					-		
				1024	Volatile Organic Compounds		

^{*} Water samples must be prepared using method 5030 (purge & trap extraction) if this test method is used.

APPROVED ANALYTICAL METHODS FOR ORGANIC COMPOUNDS

ANALYTE	SOLID No.	AND HAZARDOUS WASTE METHODS PARAMETER	I	WATE No.	R METHODS PARAMETER			
Xylene	8020* 8021* 8240 8260	Aromatic Volatile Organics Halogenated and Aromatic Volatiles Volatiles Volatiles		503.1 524.1	Volatile Org. Cmp., Purgeable Org. Cmp. Volatile Aromatic & Unsat. Organic Cmp. Purgeable Organic Compounds Purgeable Organic Compounds			
EDB	8260	Volatiles]	504 504.1	DW by Microextraction 123TCP by Microextraction & GC			
Polynuclear Aromatic Hydrocarbons	8310 8270C	Polynuclear Aromatic Hydrocarbons Semi Organic Compounds by GC/MS, Cap Column		610	Polynuclear Aromatic Hydrocarbons (High performance Liquid Chromatography)			
Lead	7420 7421	AA Direct Aspiration Atomic Absorption, Furnace Technique		200.8	Atomic Absorption Spectrometry (Graphite Furnace) Inductively Coupled Plasma Mass Spectrometry Atomic Absorption Spectrometry-Stabalized Temperature (Graphite Furnace) Method			
•	Air Sample Analysis: 40 CFR Ch. 1 (7-1-91 Edition) Part 60, Appendix A, Method 18 (Flexable Bag Procedure)							

rev 6, 07/04